



Home of the Most Productive ArchiCAD Add-ons

Hotfix 12.5

Auckland, July 16, 2009

Cadimage Tools Limited

IMPORTANT

All information contained in this document is strictly Cadimage Tools Confidential.

Contents

1.	Stair Builder	3
1.1.	Handrail bracket not connect to handrail.....	3
1.2.	Railing on Mirrored Stair	3
1.3.	Winder drops a Stringer	3
2.	Door and Window Builder	4
2.1.	Corner window problem.....	4
2.2.	Window Builder IFC problem.....	4
3.	Wall Framing.....	4
3.1.	Wall Framing Layer list	4
4.	Revision Manager	5
4.1.	Fixed an issue where Revision Manager crashes ArchiCAD	5
4.2.	Custom installation destination cause Revision Manager to fail.....	5
5.	General	5
5.1.	Cadimage Tool changes Group status	5
5.2.	Disabled interface in multiple tools.....	5

1. Stair Builder

1.1. Handrail bracket not connect to handrail


Handrail brackets sometimes do not connect to the handrail. This happens when the balustrade is offset away from the stair edge. This is now fixed.

1.2. Railing on Mirrored Stair

We fixed another issue with mirrored stair. Attach railing to a mirrored stair that includes a breakline – the railing appears in the area beyond the breakline. This will no longer occur.

1.3. Winder drops a Stringer

When you created a winder with timber stringers, one of the stringers would drop off the inside edge of the winder. This was fixed in some cases in Hotfix 4. It is now fixed in every case.



2. Door and Window Builder

2.1. Corner window problem

We discovered an issue in Hotfix 4 where corner windows do not meeting properly in corners. This is now fixed.

2.2. Window Builder IFC problem

WindowBuilder saved as an IFC file can't be brought back into ArchiCAD. Now if you set the glass thickness to a positive value, the window survives the journey to IFC and back again.

3. Wall Framing

3.1. Wall Framing Layer list

Wall framing layer list contains some duplicates and misses one layer. We have corrected this problem.

4. Revision Manager

4.1. Fixed an issue where Revision Manager crashes ArchiCAD

Revision Manager, Files saved whilst viewing a Transmittal form, Crashed when they were reopened. This will no longer occur.

4.2. Custom installation destination cause Revision Manager to fail

Revision Manager does not work properly if user installs the tool to a custom location. This is now fixed.

5. General

5.1. Cadimage Tool changes Group status

Using Cadimage Tools menu command changes the status of Suspend Groups(Mac only). This is now fixed.

5.2. Disabled interface in multiple tools

Issue discovered with caching a list of fonts. This is now fixed.